

Inspection Report (☒ 1 ST ☐ 2 ND)		PENDING	
☐ Pre-shipment ☐ ON-LINE ☐ IN PROCESS ☒ FULL			
Summary Section		Service Number: 20260416	
		Product Name	Drain cover
		Item number	/
		P/O number	/
		Quantity	2020pcs
		Client name	/
		Supplier name	Haining ZHEJIANG CO., LTD JUNE
		Inspection date	2026-04-16
		Inspection location	Haining ZHEJIANG, China
		Inspector	Lisa

Category	Conform		Comment
1. Quantity	☒ YES	☐ NO	
2. Product description / style / color	☐ YES	☒ NO	Remark 1,4
3. Workmanship	☒ YES	☐ NO	Remark 3
4. Testing/ checking	☒ YES	☐ NO	
5. Data measurement	☒ YES	☐ NO	
6. Packaging	☒ YES	☐ NO	
7. Marking	☒ YES	☐ NO	

OVERALL CONCLUSION	PENDING	

Special Attention				
1. No sample for reference during inspection. Please kindly confirm that all of information is 100% correct. 2. Factory does not allow inspector perform caron drop test. 3. Inspectors inspected total 2020 pcs of this shipment and found total 0 pcs with critical defects, _0_pcs with major defects and _82_pcs minor defects. The factory had reworked and replaced above all defects during .				
Defective products	☐ pick out	☒ replace	☒ rework	☐

Remark Picture		
	/	/

Advise for the inspection	
Require factory to rework and clean off all products on site.	

Carton packing:						
Item Name	Packing (pcs / carton)	Total carton	Carton size L × W × H (cm)	Carton G.W (Kg)	Carton Bar code	Bar code scanning
Drain cover	420	4	49X39.8X39.5	21.70	-	-

Gift box packing:				
Item Name	Packing (pcs / BOX)	Gift box size L × W × H (cm)	Gift box N.W (Kg)	Gift box Bar code
-	-	-	-	-

Product check:				
Item Name	Product size L (CM)	Product N.W (g)	UPC Bar code	Bar code scanning
Drain cove	76.36X15.54	40.11	-	-

Export carton information:					
Carton:	New export carton	Yes	Sealing :	Opaque gummed tape	/
Fastening:	Metal staples	No		Transparent gummed	Yes
Strapping:	Nylonx2	No		Paper tape	/
Material:	Ply of corrugated	5 Ply	Others:	-	/

Details Quantity

Item Name	Ordered Quantity	Total carton	Packed Quantity	Finished quantity	Not finished quantity	Sample from packed Qty.	Sample from Not packed Qty.
Drain cove	2020	4	2020	0	0	2020	0
TOTAL	2020	4	2020	0	0	2020	0

Workmanship

Inspection Standard: ANSI/ASQZ1.4 (MIL-STD-105E)			DEFECTS		
			Critical	Major	Minor
Sampling plan: Single, Normal		AQL	0	2.5	4.0
Inspection Level: Full inspection		Defects Found:	0	0	82
Sample Size:	2020pcs	Max. Allowed:	0	/	/

Defectives List				
Defectives Description		CRI	MAJ	MIN
1.	Dirty mark	0	0	82

Defectives PIC	
	
Dirty mark-minor	Dirty mark-minor
	
Dirty mark-minor	Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dent mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor



Dirty mark-minor (82pcs)



Dirty mark-minor (82pcs)

Product description



Packing



Packing



Product view



Product view



Product view



Product view



Product view



Product view

Size and weight



Carton weight check



Carton weight check



Carton size check




Carton size check




Carton size check



Carton size check



Carton size check



Carton size check



Product weight check



Product weight check



Product size check



Product size check




Carton view



Carton view



Open carton



5-ply



Packing



Packing



Packing

/

/

MARKING

SHIPPING MARK

/

/

TESTING



Smell test



Function test



Function test



Function test


INSEPCION SPOT



Factory name



Mass product



Mass product



Mass product

Note: This report reflects our findings at time and place of inspection.

This report does not relieve suppliers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter.

-----END OF REPORT-----